National Transportation Safety Board NTSB ID: DEN02LA104 Aircraft Registration Number: N2705T FACTUAL REPORT Occurrence Date: 09/05/2002 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone CO 80021 1130 MDT Broomfield Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Beech D95A Airplane Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On September 5, 2002, at 1130 mountain daylight time, a Beech D95A, N2705T, piloted by a private pilot receiving dual instruction, was substantially damaged during landing at Jefferson County Airport (BJC), Broomfield, Colorado, when the landing gear was retracted just after touchdown. Visual meteorological conditions prevailed at the time of the accident. No flight plan had been filed for the instructional flight being conducted under the provisions of Title 14 CFR Part 91. The dual student pilot and flight instructor received no injuries. The local flight originated at Broomfield, Colorado.

In his statement to a Federal Aviation Administration (FAA) inspector, the flight instructor said that the dual student was working on his multiengine airplane rating. The flight instructor said that during the landing roll, the dual student went for the wrong switch; he retracted the landing gear instead of the flaps. The flight instructor said that he "was not able to react quick enough" to stop the action. When the gear retracted, the nose struck the ground, followed by the props. The airplane traveled several hundred feet further down the runway before coming to a stop slightly right of centerline.

An FAA inspector examined the airplane at BJC. The airplane showed damage to both engine nacelles, the nose bowl, the landing gear doors, and the propellers. The examination also showed that both inboard wing ribs were bent.

The flight instructor stated that he had "discussed several times on the ground and in flight the unconventional location of the throttle, prop, landing gear, and flap controls along with the importance of identifying and verifying the appropriate control prior to engaging it."

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA104

Occurrence Date: 09/05/2002

FACTORI COMMINGE BAIL. 09/03/2002													
AVIATION Occurrent				nce Type: Accident									
Landing Facility/Approach Information	ation												
Airport Name Airpo				Airport Eleva	irport Elevation Runway Used			Runway Length			Runv	vay Width	
Jefferson County Airport KB				5670 Ft	. MSL	111	L	9000	10		100		
Runway Surface Type: Asphalt; Concre	ete												
Runway Surface Condition: Dry													
Type Instrument Approach: NONE													
VFR Approach/Landing: Full Stop; Traff	fic Pattern												
Aircraft Information													
Aircraft Manufacturer Beech			Model D95	I/Series A					Serial TD-6	Number 390			
Airworthiness Certificate(s): Normal													
Landing Gear Type: Retractable - Tricy	/cle												
Homebuilt Aircraft? No Numb	per of Seats: 5	5	Certifie	Certified Max Gross Wt. 420) LBS Number			: 2	
• • • • • • • • • • • • • • • • • • • •				Engine Manufacturer: Model/Series: Lycoming IO-360-BIB					Rated Power: 180 HP				
- Aircraft Inspection Information													
Type of Last Inspection Dat				rate of Last Inspection Time Sin			ince Last Inspection			Airfram	ne To	tal Time	
100 Hour 08			08/2002	08/2002 4 Hd					ours		6	325 Hours	
- Emergency Locator Transmitter (ELT) In	nformation												
ELT Installed? Yes ELT Operated? No				ELT Aided in Locating Accident Site? No									
Owner/Operator Information													
Registered Aircraft Owner				Street Address 11915 Airport Way									
Windsong Aviation, Inc.			City									Zip Code 80021	
				Street Address									
Operator of Aircraft				Same as Reg'd Aircraft Owner City State Zip C									
Same as Reg'd Aircraft Owner				City							Э	Zip Code	
Operator Does Business As:				O	perator Desig	nator Co	ode:						
- Type of U.S. Certificate(s) Held: None													
Air Carrier Operating Certificate(s):													
Operating Certificate:				Operator (Certificat	te:							
Regulation Flight Conducted Under: Part	t 91: Genera	I Aviatio	on	·	_	_		_	_				
Type of Flight Operation Conducted: Inst	ructional												
	F	FACTU	AL REPO	ORT - AVIAT	ION							Page 2	

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DEN02LA104

Occurrence Date: 09/05/2002

AVIATIO	Occurrence Type: Accident				1									
First Pilot Information														
Name City										ate	Date of Birth	Age		
On File	On File)			Or	n File	On File	44						
Sex: M Seat Occupied: Left Principal Profession: Unknown Certificate Number: On File											ber: On File			
Certificate(s): Private														
Airplane Rating(s): Single-engine Land														
Rotorcraft/Glider/LTA: None														
Instrument Rating(s): Airplane														
Instructor Rating(s): None														
Type Rating/Endorsement for	Accident/In	cident Aircrat	ft? No			С	urrent Bie	ennial Flig	nt Revie	ew? 06/	2002			
Medical Cert.: Class 3	Medica	l Cert. Status	: Valid Med	dicalw/ wa	aivers/lir	n.		Date o	f Last N	/ledical l	Exam: 09/2001			
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Ir Actual	nstrument Simul	ated	Rotorcraft	Glider	Lighter Than Air		
Total Time	190	10	10											
Pilot In Command(PIC)								_						
Instructor					-									
Last 90 Days		10	10											
Last 30 Days		10	10					-						
Last 24 Hours 2 2 2 Seatbelt Used? Yes Shoulder Harness Used? No							Joay Per	Performed? No Second Pilot? Yes						
Sealbell Osed: 165	31100	idei Hairiess	Used? NO			OXICO	nogy i eii	omieu: N	10		econd i not: 16	5		
Flight Plan/Itinerary														
Type of Flight Plan Filed: Nor	ne.													
									Time Zone					
Same as Accident/Incident Location						State		JC	unei	0915		MDT		
Destination							Airport Identifier							
Local Flight						State		Airport Identifier						
Type of Clearance: VFR														
Type of Airspace: Class D)													
Weather Information														
Source of Briefing: Unknown														
Method of Briefing: Unknown														
FACTUAL REPORT - AVIATION Page 3														

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: DEN02LA104

Occurrence Date: 09/05/2002

	Occurrence	Occurrence Type: Accident										
Weather	Information											
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Distance From Accider			dent Site	Direction From Accident Site)
BJC	1130	MDT	5670 Ft.	5670 Ft. MSL				NM				Mag.
Sky/Lowes	st Cloud Condition: Few	6000 Ft. AGL					Condition of Light: Day					
Lowest Ce	Ft.	AGL	Visibi	lity:	15		Altii	meter:	30.18	"Hg		
Temperatu	4 °C	4 °C Wind Direction: 90 Density Altitude: 86							8661	Ft.		
Wind Spee		Weather Condtions at Accident Site: Visual Conditions										
Visibility (F	VV)	SM Intensity of Precipitation:										
Restrictions to Visibility: None												
Type of Pr	ecipitation: None											
Accident Information												
Aircraft Da	Aircraft Fire	Aircraft Fire: None					losio	n None				
Classification: U.S. Registered/U.S. Soil												
- Injury Summary Matrix Fatal Se		rious Mino	or	None TOTAL								
First Pi	lot				1	1						
Second	d Pilot]					
Studen	t Pilot						1					
Flight I	nstructor				1	1	1					
Check	Pilot						1					
Flight E	Engineer						1					
Cabin /	Attendants						1					
Other (Crew						1					
Passer	ngers						1					
- TOTAL A	ABOARD -				2	2						
Other 0	Ground						1					
- GRANE	O TOTAL -			2 2								

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: DEN02LA104

Occurrence Date: 09/05/2002

Occurrence Type: Accident

Administrative	Information
/ tarriir ii strative	milomiation

Investigator-In-Charge (IIC)

David C. Bowling

Additional Persons Participating in This Accident/Incident Investigation:

Brian Richardson Air Carrier Maintenance Inspector Denver Flight Standards District Office 26805 East 68th Avenue, Suite 200 Denver, CO 80249